L Number	Hits	Search Text	DB	Time stamp
1	1	(non-piercing adj fastener).ti.	USPAT;	2002/10/28
			US-PGPUB;	17:01
			EPO; JPO;	İ
			DERWENT;	
2	1	/non minmaine add factor while	IBM_TDB	
-	1	(non-piercing adj fastener).ab.	USPAT;	2002/10/28
			US-PGPUB;	17:01
!			EPO; JPO; DERWENT;	
			IBM TDB	
3	3	non-piercing adj fastener	USPAT;	2002/10/28
			US-PGPUB;	17:02
			EPO; JPO;	
1			DERWENT;	
1			IBM_TDB	
4	3	(non-piercing and fastener).ti.	USPAT;	2002/10/28
			US-PGPUB;	17:02
			EPO; JPO;	
			DERWENT;	
5	8	(non-piercing and fastener).ab.	IBM_TDB USPAT;	2002/10/00
		, protoning and rabcenet/.ab.	USPAT; US-PGPUB;	2002/10/28 17:03
1	1		EPO; JPO;	17:03
			DERWENT;	
ļ			IBM TDB	
6	33	non-piercing and fastener	USPAT;	2002/10/28
	1		US-PGPUB;	17:07
			EPO; JPO;	
			DERWENT;	
7	7	(non minuminum and Early)	IBM_TDB	
'	'	(non-piercing and fastener) and (die or anvil)	USPAT;	2002/10/28
		anvii)	US-PGPUB;	17:08
	1		EPO; JPO;	1
			DERWENT; IBM TDB	
9	7	((non-piercing or non adj fastener) and	USPAT;	2002/10/28
		fastener) and (die or anvil)	US-PGPUB;	17:09
		,	EPO; JPO;	17.03
			DERWENT;	
10			IBM TDB	
10	0		USPAT;	2002/10/28
-		fastener) and (die or anvil)) not	US-PGPUB;	17:09
	ľ	((non-piercing and fastener) and (die or	EPO; JPO;	}
		anvil))	DERWENT;	1
8	50	(non-piercing or non adj fastener) and	IBM_TDB	0000/10/00
		fastener	USPAT; US-PGPUB;	2002/10/28 17:25
	:		EPO; JPO;	11.65
			DERWENT;	
1.1			IBM TDB]
11	442	29/432.2	USPAT;	2002/10/28
			US-PGPUB;	17:10
			EPO; JPO;	
	1		DERWENT;	
12	44	(non-pierc\$3 or non adj pierc\$3) and	IBM_TDB	0000/12/22
	33	fastener	USPAT;	2002/10/28
			US-PGPUB; EPO; JPO;	17:29
			DERWENT;	
			IBM TDB	
13	11	((non-pierc\$3 or non adj pierc\$3) and	USPAT;	2002/10/28
		fastener) not ((non-piercing or non adi	US-PGPUB;	17:28
		fastener) and fastener)	EPO; JPO;	
			DERWENT;	
14		(1)	IBM_TDB	
14	11	(non-pierc\$3 or non adj pierc\$3) and	USPAT;	2002/10/28
		rivets	US-PGPUB;	17:50
			EPO; JPO;	
			DERWENT;	
Search His		2/29/22 C.04.22 PM	IBM TDB	

Search History 10/28/02 6:04:33 PM Page 1

15	14	<pre>(non-pierc\$3 or non near pierc\$3) and rivets</pre>	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2002/10/28 17:38
16	7210	(deform\$3 or join\$3) and (sheet adj metal) and (die or anvil)	USPAT; US-PGPUB; EPO; JPO; DERWENT;	2002/10/28 17:44
17	36	((deform\$3 or join\$3) and (sheet adj metal) and (die or anvil)).ti.	IBM_TDB USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2002/10/28 17:47
18	419	((deform\$3 or join\$3) and (sheet adj metal) and (die or anvil)).ab.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2002/10/28 17:48
19	106	(((deform\$3 or join\$3) and (sheet adj metal) and (die or anvil)).ab.) and (process or procedure or method).ti.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2002/10/28 17:48
20	11	<pre>((((deform\$3 or join\$3) and (sheet adj metal) and (die or anvil)).ab.) and (process or procedure or method).ti.) and (fasteners or rivets).ab.</pre>	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2002/10/28 17:58
21	14	<pre>((((deform\$3 or join\$3) and (sheet adj metal) and (die or anvil)).ab.) and (process or procedure or method).ti.) and (fasteners or rivets)</pre>	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2002/10/28 17:49
22	3	<pre>(((((deform\$3 or join\$3) and (sheet adj metal) and (die or anvil)).ab.) and (process or procedure or method).ti.) and (fasteners or rivets)) not ((((deform\$3 or join\$3) and (sheet adj metal) and (die or anvil)).ab.) and (process or procedure or method).ti.) and (fasteners or rivets).ab.)</pre>	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2002/10/28 17:49
23	1	<pre>((((deform\$3 or join\$3) and (sheet adj metal) and (die or anvil)).ab.) and (process or procedure or method).ti.) and (non-pierc\$3 or non adj pierc\$3)</pre>	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2002/10/28 17:51
24	1	<pre>((((deform\$3 or join\$3) and (sheet adj metal) and (die or anvil)).ab.) and (process or procedure or method).ti.) and (non-pierc\$3 or non near pierc\$3)</pre>	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2002/10/28 17:55
25	2	(((deform\$3 or join\$3) and (sheet adj metal) and (die or anvil)).ab.) and (non-pierc\$3 or non near pierc\$3)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2002/10/28 17:55
26	42	<pre>(((deform\$3 or join\$3) and (sheet adj metal) and (die or anvil)).ab.) and (fasteners or rivets).ab.</pre>	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2002/10/28 18:01
27	57	<pre>(((deform\$3 or join\$3) and (sheet adj metal) and (die or anvil)).ab.) and (fasteners or rivets)</pre>	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2002/10/28 18:01

28	15	((((deform\$3 or join\$3) and (sheet adj	USPAT;	2002/10/28
		metal) and (die or anvil)).ab.) and	US-PGPUB;	18:01
			EPO; JPO;	
		or join\$3) and (sheet adj metal) and (die	DERWENT;	
		or anvil)).ab.) and (fasteners or	IBM TDB	
		rivotal ab l	-	1